


REV	ECO	DATE	DESCRIPTION	DB
A	3968	14-Nov-08	RELEASE TO PRODUCTION	DMD
B	4727	26-Jun-13	UPDATE INSTRUCTIONS	DMD



B PACKAGING INSTRUCTIONS:

1. LIFT LASER SLING OUT OF SHIPPING CONTAINER AND PLACE ON SOLID SURFACE.
2. REMOVE KEY FROM KEYSWITCH AT REAR OF LASER MARKER TO PREVENT DAMAGE TO KEYSWITCH ASSEMBLY.
3. PLACE LASER MARKER INSIDE FOAM CAVITIES ON LASER SLING, MAKING SURE FRONT OF LASER IS ON LEFT SIDE.
4. USE TWO OR MORE PEOPLE TO LIFT LASER MARKER/LASER SLING AND PLACE INTO BOTTOM SHIPPING CONTAINER.
5. COVER WITH TOP SHIPPING CONTAINER AND SECURE AS REQUIRED. NOTE: TOP SHIPPING CONTAINER CONTAINS FOAM CAVITIES, ORIENT FOR PROPER FIT.
6. WRITE SYNRAD RETURN AUTHORIZATION NUMBER ON OUTSIDE OF SHIPPING BOX.

IMPORTANT NOTE: FAILURE TO PROPERLY PACKAGE LASER USING SYNRAD SHIPPING BOX AND FOAM/CARDBOARD INSERTS AS SHOWN MAY VOID WARRANTY. CUSTOMERS MAY INCUR ADDITIONAL REPAIR CHARGES DUE TO SHIPPING DAMAGE CAUSED BY IMPROPER PACKAGING.

TOLERANCES UNLESS NOTED:	
.x = ± 0.1	ANGLE = ± 0.5°
.xx = ± 0.01	
.xxx = ± 0.005	
MATERIAL: SEE BOM	
FINISH:	

PROPRIETARY
THIS DRAWING IS PROPRIETARY TO SYNRAD INC. AND SHALL NOT BE USED OR DISCLOSED IN WHOLE OR IN PART WITHOUT WRITTEN PERMISSION OF SYNRAD INC.



SYNRAD INC.
4600 Campus Place
Mukilteo, WA 98275
Phone: (425)349-3500
Fax: (425)349-3667

DESCRIPTION: DOC, INSTRUCTION, PACKAGING, FENIX-FLYER			
PART NUMBER: 900-19882-01		DWG/FILE NUMBER: 900-19882-01	
SHEET 1 of 1	ENG: .	DRAWN BY: D. DUVALL	DATE: 14-Nov-08
UNITS: Inches	CATEGORY: I	CHECKED BY: <i>Phy</i>	DATE: 7-8-13
SIZE: A	FINISH CLASS: .	APPROVED BY: <i>[Signature]</i>	DATE: 7/16/13