



REV	ECO	DATE	DESCRIPTION	DB
A	4030	20-Apr-09	RELEASE TO PRODUCTION	DMD
B	4162	3-Feb-10	REPLACE CARTON, REMOVE ACC. BOX	DMD
.	.	.	.	.

**STEP BY STEP PAKAGING INSTRUCTIONS:**

1. POSITION BOX SO LOGO ON TOP FLAP IS FACING YOU (LOGO WILL BE ON THE LEFT SIDE).
2. PLACE ENDCAPS ON FRONT AND BACK OF POWER SUPPLY AS SHOWN AND SECURE IN BOX.
3. PLACE ACCESSORY BOX IN FRONT OF FOAM ENDCAP AS SHOWN.
4. CLOSE AND SEAL BOX AS REQUIRED.
5. WRITE SYNRAD RETURN AUTHORIZATION NUMBER ON OUTSIDE OF SHIPPING BOX.



**IMPORTANT NOTE:**  
FAILURE TO PROPERLY PACKAGE LASER USING SYNRAD SHIPPING BOX AND FOAM/CARDBOARD INSERTS AS SHOWN MAY VOID WARRANTY. CUSTOMERS MAY INCUR ADDITIONAL REPAIR CHARGES DUE TO SHIPPING DAMAGE CAUSED BY IMPROPER PACKAGING.

TOLERANCES UNLESS NOTED:		PROPRIETARY THIS DRAWING IS PROPRIETARY TO SYNRAD INC. AND SHALL NOT BE USED OR DISCLOSED IN WHOLE OR IN PART WITHOUT WRITTEN PERMISSION OF SYNRAD INC.		 SYNRAD INC. 4600 Campus Place Mukilteo, WA 98275 Phone: (425)349-3500 Fax: (425)349-3667	
.x = ± .1	ANGLE = ± .5 °				
.xx = ± .01					
.xxx = ± .005		DESCRIPTION: <b>PACKAGING, POWER SUPPLIES, EVO</b>			
MATERIAL: SEE BOM		PART NUMBER: 900-19886-01	DWG/FILE NUMBER: 900-19886-01		
FINISH:		SHEET 1 of 1	ENG: .	DRAWN BY: D. DUVALL	DATE: 20-Apr-09
.		UNITS: Inches	CATEGORY:	CHECKED BY: <i>[Signature]</i>	DATE: 2/4/10
.		SIZE: A	FINISH CLASS: .	APPROVED BY: <i>[Signature]</i>	DATE: 2/4/10